NATIONAL OHS ALERT



PUSH PRO SERIES ELEVATED WORK PLATFORMS ALERT

An incident has occurred in NSW where a horizontal force was applied to a Push 10 Pro EWP causing it to become unstable and tip over with a worker in the basket.

It has been concluded that the EWP is **not** fit for purpose

Push 10 Pro, Push 8 Pro and Push 6 Pro Elevated Work Platforms should not be used.

CFMEU CONSTRUCTION

ACT BRANCH (02) 6267 1599
SA BRANCH (08) 8231 5532
VIC TAS BRANCH (03) 9341 3444
NSW BRANCH (02) 9749 0400
QLD & NT BRANCH (07) 3231 4600
WA BRANCH(08) 9228 6900