

# NATIONAL SAFETY ALERT

## Crane Safety Alert

### Yong Mao STT 293 Tower Cranes

**This health and Safety alert is a result of an inspection by the crane operator of the slew ring after hearing a clunk whilst lifting and slewing a shutter.**

On inspection the crane operator found that one of the slew ring teeth had been dislodged.

A crack test was conducted on the remaining slew ring teeth which found that each tooth of the slew ring failed that crack test.

#### **ACTION REQUIRED**

Immediately have all Yong Mao STT 293 tower Cranes removed from service until the slew ring is independently inspected and crack tested by a suitably qualified engineer.

Evidence of the completed inspection results must be forwarded to the CFMEU Health and Safety Co-ordinators before the tower crane can be returned to service.

#### **CFMEU ACT Branch:**

02 6267 1599

#### **CFMEU QLD/NT Branch:**

07 3231 4600

#### **CFMEU NSW Branch:**

02 9749 0400

#### **CFMEU SA Branch:**

08 8231 5532

#### **CFMEU WA Branch:**

08 9221 1055

#### **CFMEU VIC/TAS Branch:**

03 9341 3444



*Safety is union business.*

**STAND UP. SPEAK OUT. COME HOME.**